Work Order ID 57291

Tuesday, April 06, 2010 10:15:08 AM



Page 1

Item ID: D206-559-021 Revision ID: Item Name: Bearpaw

Start Date:

Reference:

3/31/2010 Required Date: 3/31/2010

Start Qty: 1.00 Req'd Qty: 1.00

Return 2010 / RA110012

Accept

Setup Start

Stop



Approvals: Process Plan:

Date:

Tooling:

Date: 1005/06 SPC (Y/N):

Date:

Date:

Cust Item ID:

Customer:

Run Start

Stop

Sequence ID/ Work Center ID

Operation Description Set Up/ **Run Hours** Draw Number Draw Rev.

Plan Accept Code Oty

Reject Reject Qty Number

Insp. Stamp

Draw Nbr Revision Nbr IIN-D206-559 J-PRELIM

100

QC5- Inspect part completeness to step on W/O

0.00

0.00

QC

Quality Control

Memo

Orignal B42825.

Kit was used, & needs to be replaced.

110

Packaging Packaging

Pick Kit

0.00

0.00

Memo

Pick new kit.

New labels & decals, paperwork required with the new batch #

Af for CL 10/04/09

Use the original bearpaw batch # for the bearpaws when picking. DO not pull stock.

10-4-16 5/

Work Order ID 57291

Tuesday, April 06, 2010 10:15:08 AM



Page 2

Item ID:

D206-559-021

Accept

Setup Start



Revision ID:

Item Name:

Bearpaw

QC:

Start Date: 3/31/2010 Required Date: 3/31/2010 Start Qty: 1.00

Req'd Qty: 1.00

Date:_____

Cust Item ID:

Customer:

Reference:

Return 2010 / RA110012

Approvals:

Process Plan:

Date:

Tooling:

Set Up/

Run Hours

SPC (Y/N):

0.00

Date:

Date:

Run

Start

Stop



Stop

Sequence ID/ Work Center ID

120

QC

Operation Description

QC4- 100% Inspect kits for completeness

Draw Number

Draw Plan Rev.

Accept Code Otv

Reject Oty

Reject Number

Insp. Stamp

Quality Control

130

Packaging

Packaging

Memo

Memo

Identify as per dwg & Stock Location:

NevA

0.00

0.00

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Warehouse

Loc Oty

160

Loc Code

0.0000

Location

Main Warehouse

ST359

990

112314

No

Purchased

990 Each 16.0000

M113706 10-4-164

11AS/149104634

Washer

Picklist Print

Tuesday, April 06, 2010 10:15:07 AM

Required Date: 3/31/2010

Required Qty: 1.00

Work Order ID: 57291

Parent Item:

Comments:

D206-559-021

Parent Item Name:

Bearpaw

IPP Rev:F

IPP Rev:C□04.02.17□Blank size changed□KJ/JLM□ IPP Rev:D 07-01-02 Was K10005

08-05-05

IPP Rev:E 08-01-09

JLM Added Step 2 JLM

up a chg DD verified by:EC

79-625.0n

Manufactured

Manufactured

160

f

Loc Oty

12

12

Each

391.25

403.2500 1.6700

Loc Code

Start Date: 3/31/2010

Start Qty: 1.00

10-4-16

Rubber Cushion

J MESSARP

No

Warehouse Location

Main Warehouse ST402A

30872

Verified By:EC

Main Warehouse

ST410

52649

391.25 160

193.0000 8.0000

Radius Block

Warehouse Loc Qty Location Main Warehouse ST010 193 55602 76 56686 117 Loc Code

Tuesday, April 06, 2010 10:15:07 AM

Work Order ID: 57291

D206-559-021

Parent Item: Parent Item Name:

Bearpaw

Comments:

IPP Rev:C□04.02.17□Blank size changed□KJ/JLM□

IPP Rev:D 07-01-02 IPP Rev:E 08-01-09

Was K10005 Added Step 2

Manufactured

Manufactured

Manufactured

JLM Verified By:EC

JLM

IPP Rev:F

08-05-05

up a chg DD verified by:EC

No

No

No

160

Each

Start Date: 3/31/2010

Required Date: 3/31/2010

Start Qty: 1.00

Required Qty: 1.00

137.0000 4.0000

D2438_

Clamp

Loc Oty Loc Code Warehouse Location Main Warehouse ST456 137

37 55603 100

160 Each

218.0000 8.0000



10-4-10

Washer

Loc Oty Loc Code Warehouse Location

160

Main Warehouse

ST017

218

56184

218 Each

0.0000 2.0000

B43835 10-4-165f



Picklist Print

Tuesday, April 06, 2010 10:15:07 AM

Work Order ID: 57291

Parent Item: D206-559-021

Parent Item Name: Bearpaw

Comments:

IPP Rev:C□04.02.17□Blank size changed□KJ/JLM□

IPP Rev:D 07-01-02 IPP Rev:E 08-01-09

Was K10005 Added Step 2

JLM JLM Verified By:EC

IPP Rev:F 08-05-05 up a chg DD verified by:EC

MS21042LA

Purchased

No

160

Each

Start Date: 3/31/2010

Required Date: 3/31/2010

Start Qty: 1.00

Required Qty: 1.00

1,641.000-8.0000

16-4-1650

Warehouse	Loc	Loc Oty	
Location			
Main Warehouse			
ST139		2	
111827		2	
Main Warehouse			
ST300		1639	
113422		631	
114108	1000		
9063		8	
	160	Each	12.0000

Purchased

No

Loc Oty

12 12 12.0000 2.0000

10-4-16

Clamp

Warehouse	
Location	
Main Warehouse	
ST450	
113288	

Loc Code

REFERENCE ONLY

DART AEROSPACE LTD.

D206-559 Page 7 of 13

5.0 PARTS LIST



Qty	Qty	/Qty)	Qty	Qty	Qty	Qty	Part Number	Description	
-011	-013	(-021°	-023	-031	-033	-113			
X							D206-559-011	Bearpaw Kit 206 A/B	
	Х						D206-559-013	Bearpaw Kit 206 L/L1/L3/L4/407	
		х					D206-559-021	Narrow Bearpaw Kit 206 A/B	
			Х				D206-559-023	Narrow Bearpaw Kit 206 L/L1/L3/L4/407	
				Х			D206-559-031	Wearplate Kit	
					Х		D206-559-033	Wearplate Kit	
						Х	D407-559-113	Large Bearpaw Kit 206 L/L1/L3/L4/407	
4	6	4	16			1	D2182B050 /	RUBBER CUSHION	
8	12	=8 <	12			20	(D2274	RADIUS BLOCK	
2 -							D2435	19" X 16" BEARPAW	
	2	 			-	•	D2432F	19" X 24" BEARPAW	
		2	 				D2671 /	13" X 16" BEARPAW	
	•		2				D2672F	13" X 24" BEARPAW	
4	. 6	4 لـ	- 6		,		D2438 J	CLAMP	
8	12	8	12		ŧ.		D2529 /	WASHER	
	6	,	6		1,1		D2732-050	RUBBER CUSHION	
						2	D3456-1	WASHER	
					2		D3859-041	WEARPLATE	
				2			D3860-041	WEARPLATE	
			-			2	D4010-041	BEARPAW ASSEMBLY	
						8	D4011-1	CLAMP, SHORT	
						2	D4011-3	CLAMP, LONG	
						8	D4011-5	CLAMP, SHORT (OEM)	
		· ·				10	D4012-1	CUSHION	
	! !	<u> </u>				2	AN4C10A	BOLT	
8	12 (8	7 12	8	12		AN4-15A-	BOLT	
8	12	8	712	8	12		AN4-17A /	BOLT	
	-			i	-	4	AN4C13A	BOLT	
		1	1			8	AN4C15A	BOLT	
			ì		;	8	AN4C17A	BOLT	
16	24	/ 16	724		1.		AN960JD416,	WASHER	
8	.12	8 .	r 12	8	12	ı	MS21042L4 /	NUT (OR MS21042-4)	
		-	<u> </u>		· ·	20	MS21043-4	NUT	
		1	<u> </u>	8	12		NAS1149D0463J	WASHER	
2	ļ	2_	1			ŧ	QS200M44S /	CLAMP	

Revision: K

Date: 09.11.16

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES												
DATE	STEP	PROC	PROCEDURE CHANGE				Approval Chief Eng / Prod Mgr	Approval QC Inspector						
	,		•											
							_							
-														
Part No	:	PAR #:	_ Fault Ca	tegory:	NCR: Yes	No DQA:	Date: _							
Resolution:														
NCR:		, W	ORK OR	DER NON-CONFORMA	NCE (NCR	')								
DATE STE	STED	Description of NC	Corrective Action Section			Verification		Approval						
	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	QC Inspector						
								-						
		,												
		·												
	I	· ·	1		ł	1	1	ľ						

NOTE: Date & initial all entries